UI Bulletin #167b

Subject:	HD Pickup Box Removal / ZW9 Capped Fuel Filler Assembly Components
Models:	Chevrolet Silverado/GMC Sierra Heavy Duty Pickup – 56" CA `Long Box'
Model Years:	2020 and Beyond
Date:	May 14, 2020
Revision Date	N/A

ADVISORY:

This GM UI Bulletin is designed to assist Upfitters with Fuel Filler Assembly Components for `Pickup Box Removal' applications.

Condition/Concern:

C/K HD 56" CA `Long Box' models are approved for `Pickup Box Removal' provided the upfit body is refitted with approved RPO-ZW9 Capped Fuel Fill Assembly Components. Care must be taken to follow GM UI BBM Fuel Fill Installation & Positioning Guidelines and when installing upfit bodies on the chassis.

Recommendation:

Upfitters should use the following combination of approved RPO- ZW9 Fuel Filler Components for completing `Pickup Box Removal' upfit applications:

GAS (FJW) -*Shown on Page 2*

DIESEL (FHX) *- Shown on Page 3*

***Note temporary idled assembly plant and dealer parts distribution challenges may affect GM Service Part availability.**

Additional Information:

Refer to GM UI BEST PRACTICES `CHASSIS' Section regarding routing & serviceability and securing hose assembly. http://www.gmupfitter.com

Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.

GAS PU Box Removal' GM Service Parts



84709155 HD Pickup ZW9 `GAS'(FJW) Fuel Fill Assembly (above)

`Bag in Cab' Parts (below)


84451003_002-HOSE ASM-F_TNK FIL_4099
84723291_001-PIPE-F_TNK FIL LWR - GAS_3984
ANU00192_001-INSTALLED 84179474 - CLAMP-F_TNK FIL HOSE_70806
ANU00192_001-INSTALLED 84179474 - CLAMP-F_TNK FIL HOSE_70806
84451004_002-PIPE ASM-F_TNK FIL_3984

Part Number	Qty	Description
84451004	1	Pipe Assembly – Fuel Tank Fill
84179474	2	Clamp-Fuel Tank Fill Hose
84451003	1	Hose Assembly – Fuel Tank Fill
84179474	2	Clamp-Fuel Tank Fill Hose
84723291	1	Parts Pkg – Fuel Tank Fill Pipe
22921365	1	Cap-Gas

Use above ZW9 `GAS' `Bag in Cab' P/Ns (POA 84818645)

Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.

DIESEL PU Box Removal' GM Service Parts



84861894 HD Pickup ZW9 `DIESEL'(FHX) Fuel Fill Assembly (above)

`Bag in Cab' Parts (below)


84451028_002:HOSE ASM:F_TNK FIL_4099
ANU01863_002:INSTALLED 84179474 : CLAMP : F_TNK FIL HOSE_9097
84451026_002:PIPE ASM:F_TNK FIL_3984
ANU01863_002:INSTALLED 84179474 : CLAMP : F_TNK FIL HOSE_9097

Part Number	OTY	Description
84451026	1	Pipe Assembly – Fuel Tank Fill
84451028	1	Hose Assembly – Fuel Tank Fill
84179474	2	Clamp-Fuel Tank Fill Hose
23288713	1	Cap-Diesel

Use above ZW9 `DIESEL' `Bag in Cab' P/Ns (POA 84818644)

Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.